

**Table 10**  
**Finding of Suitability for Early Transfer**  
**Summary of Buildings Surveyed for the Presence of Lead-Based Paint (1995 and 2000)**  
**Fort McClellan, Calhoun County, Alabama**

Building No.	Description	LBP Present		LBP Condition/Location I - Interior      E - Exterior	Lead Dust Exceed Standard (µg/ft <sup>2</sup> ) <sup>a</sup>	Soil Lead Exceed 400 ppm
		Interior	Exterior			
1740	Chapel	Yes	Yes	Fair: I – Room 1: White metal rafter, Room 2: White metal door and casing, Room 3: Tan concrete wall  Poor: I – Room 1: White metal sash, Room 6: White metal window sash. E – Brown concrete pad	None	1590 ppm within 3 ft of the building
3337	Avery Family Housing	Yes	Yes	I-Shelves, shelf supports, baseboards, curtain molding E- Porch ceiling, trim, column, support; wood rail, wood fences, concrete slab	None	None

<sup>a</sup> Results for the 2000 LBP surveys and risk assessment Phase I, all other results are for the 1995 LBP surveys.